



Photo 1: The piano as it looks when it arrives at the shop



Photo 2: Fallboard decal



Photo 3: 2nd decal – this one may not be available to replace



Photo 4: View from other side.



Photo 5: Piano action remove to bench for servicing



Photo 6: Quite Case parts and keyset removed and put on piano parts trolley



Photo 7: Piano is placed on piano cradle – end of 1st day's work..

Next step – Dave will finish disassembling the case and begin stripping parts.