



*Photo 1: The movers arrive at the shop*



*Photo 2: The right equipment always helps*



*Photo 3: The piano at first glance*



*Photo 4: A few keys are a bit sluggish.*



*Photo 5: Keytops? Who needs keytops?*



*Photo 6: Quite possibly a mouse had found his way in here. (The real mess was under the keys)*



*Photo 7: A well read copy of the Reader's Digest*



*Photo 8: A sure sign that the piano has been enjoyed.*



*Photos 9 – 14: Teardown of piano begins*



*Photo 15: Piano on its back for additional disassembly*



*Photo 16: Back and pinblock that is rock solid – like it was built yesterday*



*Photo 17: You can still see the bubbles in the glue!*



*Photo 18: Removal of the legs*

Next step – Dave will finish disassembling the case and begin stripping parts. I'll be removing pins and strings. More pictures to follow.